

Product Safety Recall

DRIVETECH BY RIVAL ALUMINIUM REAR BAR WITH TOW BAR



Part/No - Invoice	Description	Part/No - On item	Make and model
DT-2D18111	RIVAL ALUMINIUM REAR BAR	2D.1811.1-NL	FORD RANGER PX - PXIII - 09/11 - 05/22
DT-2D40031	RIVAL ALUMINIUM REAR BAR	DT-2D40031NLRM	MITSUBISHI TRITON MQ - 03/15 to 10/18
DT-2D41111	RIVAL ALUMINIUM REAR BAR	DT-2D41111NLRM	NISSAN NAVARA D23 - 2015 Onward
DT-2D57151	RIVAL ALUMINIUM REAR BAR	2D.5715.1-NL	TOTOTA HILUX 2011-Onward
DT-2D58061	RIVAL ALUMINIUM REAR BAR	2D.5806.1-NL	VW AMAROC 2H - 01/11 Onward
DT-2D91021	RIVAL ALUMINIUM REAR BAR	DT-2D91021NLRM	ISUZU D-MAX TF II - 2012 - 2020

Distributed by Motospecs and NAPA Auto Parts through a range of 4X4 resellers operating nationally from March 2019 to December 2021 and Repco stores from August 2020 to October 2021

Defect: The bolts that secure the hitch receiver to the tow bar, may have a different thread to the nuts in the tow bar and may loosen. On the Amaroc application, the bolts may “bottom out” before fully tightening.

Hazard: If the towbar detaches from the vehicle while towing, this could cause the trailer to separate from the towing vehicle. This could increase the risk of an accident causing serious injury or death.

What to do: Consumers should not tow a trailer with the product affected by this recall. Take the vehicle to the place where the product was purchased and installed to arrange for an inspection. The product will be repaired, or if necessary, replaced or refunded. If you are a significant distance from the place of purchase, please contact the number below for information concerning a suitable location for inspection.

Contact details: For further information please contact NAPA customer service on 1800 605 673 or email recall@napaparts.com.au

**See productsafety.gov.au for
Australian product recall information**